




Drawbar position gauges are used to adjust and set drawbar stroke position on HSK machine tool spindles. The gauges allow the clamping angle to be adjusted to the high and low limits, allowing the stroke position to be set.

Taper	Part Number
HSK-A/E 40	470.210.140.000
HSK-A/E 50	470.210.150.000
HSK-A/E 63	470.210.163.000