

For cleaning the bore of the tool holder. E.g. hydraulic chucks and shrink fit chucks.

| Mandrel Ø (d1) | Length (l2) | Ø (d2) | l1 | Part Number |
|----------------|-------------|--------|-----|---------------------------------|
| 6 | 37 | 24 | 158 | 530.120.006.000 |
| 8 | 37 | 24 | 158 | 530.120.008.000 |
| 10 | 47 | 24 | 168 | 530.120.010.000 |
| 12 | 47 | 24 | 168 | 530.120.012.000 |
| 14 | 47 | 24 | 168 | 530.120.014.000 |
| 16 | 70 | 24 | 176 | 530.120.016.000 |
| 18 | 70 | 24 | 176 | 530.120.018.000 |
| 20 | 70 | 24 | 176 | 530.120.020.000 |
| 25 | 80 | 24 | 186 | 530.120.025.000 |
| 32 | 100 | 30 | 221 | 530.120.032.000 |
| 40 | 105 | 30 | 226 | 530.120.040.000 |

TAC Rockford Product Line

Machine Tool Gauges, Tool Changer Alignment, Runout Test Arbors, Workholding Systems, Tool Holders, Adapters and Extensions, Tool Holder Blanks, Machine Tool Accessories, Coolant Tubes and Gauges, Heat Shrink Systems, Rapid Prototyping


Tool Holders



Gauges



Accessories



Rapid Prototyping

