

The pressure ball screw must be secured with Loctite 222. Includes pressure ball screw.

Taper (d1)	B	Ø (d1)	d2	G	Part Number
HSK-C 25	7	25	28.0	M3.5	683.4953.025.000
HSK-C 32	7	32	35.0	M4	683.4953.032.000
HSK-D 32	7	32	35.0	M3.5	683.4953.032.019
HSK-C 40	9	40	43.5	M5	683.4953.040.000
HSK-D 40	9	40	43.5	M4	683.4953.040.024
HSK-C 50	11	50	54.0	M6	683.4953.050.000
HSK-D 50	11	50	54.0	M5	683.4953.050.030
HSK-D 63	14	63	68.0	M6	683.4953.063.038
HSK-C 80	17	80	85.0	M10	683.4953.080.000
HSK-D 80	17	80	85.0	M8	683.4953.080.048
HSK-C 100	23	100	105.0	M12	683.4953.100.000
HSK-D 100	23	100	105.0	M10	683.4953.100.060
HSK-D 125	23	125	130.0	M12	683.4953.125.075

TAC Rockford Product Line

Machine Tool Gauges, Tool Changer Alignment, Runout Test Arbors, Workholding Systems, Tool Holders, Adapters and Extensions, Tool Holder Blanks, Machine Tool Accessories, Coolant Tubes and Gauges, Heat Shrink Systems, Rapid Prototyping


Tool Holders



Gauges



Accessories



Rapid Prototyping

